



FI Light Fix for:

2005-2011 Kawasaki ZX6R/ZX6R

2004-2011 Kawasaki ZX-10


2006-2011 GSX-R600/750

2001-2011 Suzuki GSX-R1000

2008-2011 Suzuki B-King

To eliminate the fuel injection light from staying illuminated:

1. Remove the seat and locate the servo motor with the two cables running to the exhaust butterfly valve.
2. Disconnect and remove cables.
3. Remove the centre screw and pulley from motor and replace with Hindle servo plate.
4. The plate is placed slot down with curved edge facing towards cable block.
5. Use lock-tight on the 10mm bolt to secure plate in place.



**We recommend that this be installed by a qualified motorcycle technician*.*